



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

Department of Environmental Management  
DIVISION OF SITE REMEDIATION  
291 Promenade Street  
Providence, R.I. 02908-5767

Robert Krivinskas, Remedial Project Manager  
US Department of the Navy  
NAVFACENGCOM- Northern Division  
Code 1823, Mail Stop #82  
10 Industrial Highway  
Lester, PA 19113-2090

7 February 1995

RE: WATER LINE REPAIRS  
SITE 06, SOLVENT DISPOSAL AREA  
Naval Construction Battalion Center, Davisville Rhode Island

Dear Bob:

The Department is aware of the Navy's plans for emergency repairs to the leaky water valve in the vicinity of Site 06. I have reviewed the TCLP results for subsurface soil samples obtained from Site 06. The TCLP extraction results for subsurface soil sample B-06-03-02 indicate the presence of Barium at an elevated level of 100 mg/l. Of the subsurface soil samples subjected to TCLP analysis this was the only sample and only constituent which approached regulatory levels for hazardous waste classification.

Please be advised that it is the responsibility of the generator to properly characterize wastes. If the material excavated during repair activities would not be considered hazardous under The Rules and Regulations for Hazardous Waste Generation, Transportation, Treatment, Storage and Disposal then the excavated material may be placed back into the trench.

If I can be of further assistance to you please feel free to call me at (401) 277-3872 extension 7142.

Sincerely,

Judith Graham  
Engineer

cc: W. Angell, DEM DSR  
R. Gottlieb, DEM DSR  
C. Williams, USEPA Region 1

ncbc.6v/jg